

Mine Name: Aragonite

Inspector(s): L. Heppler

Operator Name: Star Stone Quarries, Inc

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

Date: March 15, 2009

Reviewed:	1-

Permit Number: S/045/0031

Inspection Date: 10-29-2008

Time: 12:50 PM

Anopeetor(b). El reppier	Time, Index Ind		
Other Participants: none	Mine Status: ACT		
Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$		
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,			
8. Soils	\boxtimes		
9. Revegetation	\boxtimes		

Bond Renewal Date: 05-01-1991. Bond Amount: \$13,630 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection

Inspection Summary: Trash piles are all over the site. Nothing has been down to salvage topsoil. No new revegation efforts have been done.

Photos were taken to document site conditions.

Conclusions and Recommendations: Bond needs to be escalated. Numerous trash piles on site need to be removed. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Lon Thomas

O:\M045-Tooele\S0450031-Aragonite\inspections\insp_10292008.doc

